



Fabric Chart & Temperature Rating

<u>Cloth</u>	<u>Temperature</u>
16 oz. Aluminized Rayon	350 – 450°F
19 oz. Aluminized Kevlar	500 - 600°F
22 oz. Kevlar	500 - 600°F
24 oz. Terry Kevlar	500 - 600°F
22 oz. P.B.I.	700 - 1000°F
14 oz. Aluminized Carbon Kevlar	700 - 1000°F
19 oz. Aluminized Carbon Kevlar	700 - 1000°F
26 oz. Vertex Glass	1200 - 1800°F
36 oz. Vertex Glass	1200 - 1800°F
Stainless Steel	1800 - 2000°F